



> 1 ASSOC CITY:	LONELY	4 STATE:	AK	LOC ID:	AK71	FAA SITE NR:	50453.*A
> 2 AIRPORT NAME:	LONELY AS			5 COUNTY:	BARROW AK		
3 CBD TO AIRPORT (NM):	00 N	6 REGION/ADO:	AAL/NONE	7 SECT AERO CHT:	POINT BARROW		

GENERAL		SERVICES		BASED AIRCRAFT	
10 OWNERSHIP:	AIR FORCE	> 70 FUEL:		90 SINGLE ENG:	0
> 11 OWNER:	U.S. AIR FORCE			91 MULTI ENG:	0
> 12 ADDRESS:	611TH AIR SUPPORT GROUP, 10471 20TH STREET, ELMENDORF AFB, AK 99506			92 JET:	0
> 13 PHONE NR:	907-552-3442			93 HELICOPTERS:	0
> 14 MANAGER:	NICK HILTON			TOTAL:	0
> 15 ADDRESS:	611TH AIR SUPPORT SQUADRON, 10471 20TH ELMENDORF AFB, AK 99506			94 GLIDERS:	0
> 16 PHONE NR:	907-552-4400			95 MILITARY:	0
> 17 ATTENDANCE SCHEDULE:	UNATNDD			96 ULTRA-LIGHT:	0
		FACILITIES			
		> 80 ARPT BCN:	WG		
		> 81 ARPT LGT SKED :			
		BCN LGT SKED:	SEE RMK		
		> 82 UNICOM:			
		> 83 WIND INDICATOR:	YES		
18 AIRPORT USE:	PRIVATE	84 SEGMENTED CIRCLE:	NONE		
19 ARPT LAT:	70-54-38.6830N ESTIMATED	85 CONTROL TWR:	NO		
20 ARPT LONG:	153-14-31.9740W	86 FSS:	BARROW		
21 ARPT ELEV:	17.0 ESTIMATED	87 FSS ON ARPT:	NO		
22 ACREAGE:		88 FSS PHONE NR:	907-852-2511		
> 23 RIGHT TRAFFIC:	NO	89 TOLL FREE NR:	LC852-2511		
> 24 NON-COMM LANDING:	NO				
RUNWAY DATA					
> 30 RUNWAY INDENT:		07/25			
> 31 LENGTH:		5,000			
> 32 WIDTH:		100			
> 33 SURF TYPE-COND:		GRAVEL			
LIGHTING/APCH AIDS					
> 40 EDGE INTENSITY:		MED			
> 42 RWY MARK TYPE-COND:		NONE - / NONE - - / - - / -			
OBSTRUCTION DATA					
50 FAR 77 CATEGORY		/	/	/	/
> 51 DISPLACED THR:		/	/	/	/
> 52 CTLG OBSTN:		/	/	/	/
> 53 OBSTN MARKED/LGTD:		/	/	/	/
> 54 HGT ABOVE RWY END:		/	/	/	/
> 55 DIST FROM RWY END:		/	/	/	/

> ARPT MGR PLEASE ADVISE FSS IN ITEM 86 WHEN CHANGES OCCUR TO ITEMS PRECEDED BY >

> 110 REMARKS

A 014 DEPUTY INSTALLATION MANAGER.

A 018 CLOSED TO THE PUBLIC. BUREAU OF LAND MANAGEMENT (BLM) MANAGED FACILITY.

A 081 24 HRS

A 110-001 ALL ACFT OPERATORS SHALL OBTAIN WRITTEN AUTHORIZATION PRIOR TO LANDING. CTC THE BLM ARCTIC FIELD OFFICE, 1150 UNIVERSITY AVENUE, FAIRBANKS, AK 99709 OR CALL 907-474-2200 TO APPLY FOR AN AUTHORIZATION 45 DAYS PRIOR TO INTENDED LANDING. FAILURE TO OBTAIN AND HAVE ONBOARD AN APPROVED AUTHORIZATION MAY RESULT IN TRESPASS VIOLATIONS AND POSSIBLY CRIMINAL AND CIVIL ACTION.

A 110-002 CAUTION: RWY NOT MAINTAINED, RECOMMEND VISUAL INSPECTION PRIOR TO LDG.

111 INSPECTOR:	( F )	112 LAST INSP:	07/12/1977	113 LAST INFO REQ:	05/18/2007
----------------	-------	----------------	------------	--------------------	------------