

AIRPORT MASTER RECORD

Data Source: https://www.faa.gov/air_traffic/flight_info/aeronav/aero_data/

PRINT DATE: 7/4/2026
AFD EFF 06/11/2026

> 1 ASSOC CITY: NEW STUYAHOK 4 STATE: AK LOC ID: KNW FAA SITE NR: 50528.7*A
 > 2 AIRPORT NAME: NEW STUYAHOK 5 COUNTY: DILLINGHAM AK
 3 CBD TO AIRPORT (NM): 01 W 6 REGION/ADO: AAL/NONE 7 SECT AERO CHT: KODIAK

GENERAL

10 OWNERSHIP: PUBLIC
 > 11 OWNER: ALASKA DOT&PF CENTRAL REGION
 > 12 ADDRESS: PO BOX 196900
 ANCHORAGE, AK 99519-6900
 > 13 PHONE NR: 907-269-0749
 > 14 MANAGER: KEVIN HARDIN
 > 15 ADDRESS: BOX 250
 DILLINGHAM, AK 99576
 > 16 PHONE NR: 907-842-5511
 > 17 ATTENDANCE SCHEDULE:
 UNATNDD

SERVICES

70 FUEL:
 71 AIRFRAME RPRS:
 72 PWR PLANT RPRS:
 73 BOTTLE OXYGEN:
 74 BULK OXYGEN:
 75 TSNT STORAGE:
 76 OTHER SERVICES:

OPERATIONS

Information on aircraft operations is available from FAA's Aviation System Performance Metrics <https://aspm.faa.gov>

FACILITIES

18 AIRPORT USE: PUBLIC
 19 ARPT LAT: 59-27-05.5000N ESTIMATED
 20 ARPT LONG: 157-22-23.4000W
 21 ARPT ELEV: 370.7 SURVEYED
 22 ACREAGE:
 > 23 RIGHT TRAFFIC: NO
 > 24 NON-COMM LANDING: NO
 25 NPIAS/FED AGREEMENTS: NGY
 > 26 FAR 139 INDEX:

80 ARPT BCN: WG
 81 ARPT LGT SKED : SEE RMK
 BCN LGT SKED: SEE RMK
 82 UNICOM:
 83 WIND INDICATOR: YES-L
 84 SEGMENTED CIRCLE: YES
 85 CONTROL TWR: NO
 86 FSS: DILLINGHAM
 87 FSS ON ARPT: NO
 88 FSS PHONE NR: 907-842-5275
 89 TOLL FREE NR: LC842-5275

RUNWAY DATA

> 30 RUNWAY INDENT:
 > 31 LENGTH:
 > 32 WIDTH:
 > 33 SURF TYPE-COND:
 > 34 SURF TREATMENT:
 35 GROSS WT: S
 36 (IN THSDS) D
 37 2D
 38 2D/2D2
 > 39 PCN:

14/32
 3,281
 75
 GRVL-G
 NONE

LIGHTING/APCH AIDS

> 40 EDGE INTENSITY:
 > 42 RWY MARK TYPE-COND:
 > 43 VGSF:
 44 THR COSSING HGT.:
 45 VISUAL GLIDE ANGLE:
 > 46 CNTRLN-TDZ:
 > 47 RVR-RVV:
 > 48 REIL:
 > 49 APCH LIGHTS:

MED				
- / -	- / -	- / -	- / -	- / -
P4L / P4L	/	/	/	/
25 / 25	/	/	/	/
3.00 / 3.00	/	/	/	/
- / -	- / -	- / -	- / -	- / -
- / -	- / -	- / -	- / -	- / -
Y / Y	/	/	/	/
/	/	/	/	/

OBSTRUCTION DATA

50 FAR 77 CATEGORY
 > 51 DISPLACED THR:
 > 52 CTLG OBSTN:
 > 53 OBSTN MARKED/LGTD:
 > 54 HGT ABOVE RWY END:
 > 55 DIST FROM RWY END:
 > 56 CNTRLN OFFSET:
 57 OBSTN CLNC SLOPE:
 58 CLOSE-IN OBSTN:

A(V) / A(V)	/	/	/
/	/	/	/
/	/	/	/
/	/	/	/
/	/	/	/
/	/	/	/
/	/	/	/
20:1 / 20:1	/	/	/
N / N	/	/	/

DECLARED DISTANCES

> 60 TAKE OFF RUN AVBL (TORA):
 > 61 TAKE OFF DIST AVBL (TODA):
 > 62 ACLT STOP DIST AVBL (ASDA):
 > 63 LNDG DIST AVBL (LDA):

/	/	/	/
/	/	/	/
/	/	/	/
/	/	/	/

> 110 REMARKS

A 030 RWY 14/32 DOWN SLOPE TOWARD SE. SOFT WHEN WET. NMRS DIPS MIDFIELD.
 A 075 TIE DOWN ROPES NOT AVBL.
 A 081 ACTVT REIL RWY 14 & 32; PAPI RWY 14 & 32; MIRL RWY 14/32 - CTAF.
 A 081 ACTVT ROTG BCN - CTAF.
 A 110-010 WX CAMERA AVBL ON INTERNET AT [HTTPS://WEATHERCAMS.FAA.GOV](https://weathercams.faa.gov)
 A 110-012 BANK EROSION AT RAMP, TXY & OVRNS.

111 INSPECTOR: (C)

112 LAST INSP: 06/24/2024

113 LAST INFO REQ:

AIRPORT MASTER RECORD

Data Source: https://www.faa.gov/air_traffic/flight_info/aeronav/aero_data/

PRINT DATE: 7/4/2026
AFD EFF 06/11/2026