

AIRPORT MASTER RECORD

Data Source: https://www.faa.gov/air_traffic/flight_info/aeronav/aero_data/

PRINT DATE: 5/16/2026
AFD EFF 05/14/2026

> 1 ASSOC CITY: TIFTON 4 STATE: GA LOC ID: TMA FAA SITE NR: 04057.*A
 > 2 AIRPORT NAME: HENRY TIFT MYERS 5 COUNTY: TIFT GA
 3 CBD TO AIRPORT (NM): 02 SE 6 REGION/ADO: ASO/ATL 7 SECT AERO CHT: JACKSONVILLE

GENERAL

10 OWNERSHIP: PUBLIC
 > 11 OWNER: TIFTON & TIFT CO ARPT AUTH.
 > 12 ADDRESS: PO BOX 826
 TIFTON, GA 31793
 > 13 PHONE NR: 229-391-3535
 > 14 MANAGER: ERIC RICHTER
 > 15 ADDRESS: 3093 US HIGHWAY 41 S
 TIFTON, GA 31794
 > 16 PHONE NR: 229-425-1791
 > 17 ATTENDANCE SCHEDULE:

ALL MON-FRI 0700-1700
 ALL SAT-SUN 0800-1700

SERVICES

70 FUEL: 100LL A+
 71 AIRFRAME RPRS: MAJOR
 72 PWR PLANT RPRS: MAJOR
 73 BOTTLE OXYGEN: NONE
 74 BULK OXYGEN: NONE
 75 TSNT STORAGE: TIE
 76 OTHER SERVICES: INSTR

OPERATIONS

Information on aircraft operations is available from FAA's Aviation System Performance Metrics <https://aspm.faa.gov>

FACILITIES

80 ARPT BCN: WG
 81 ARPT LGT SKED : SEE RMK
 BCN LGT SKED: SS-SR
 82 UNICOM: 122.700
 83 WIND INDICATOR: YES-L
 84 SEGMENTED CIRCLE: YES
 85 CONTROL TWR: NO
 86 FSS: MACON
 87 FSS ON ARPT: NO
 88 FSS PHONE NR:
 89 TOLL FREE NR: 1-800-WX-BRIEF

18 AIRPORT USE: PUBLIC
 19 ARPT LAT: 31-25-46.4000N ESTIMATED
 20 ARPT LONG: 083-29-21.2000W
 21 ARPT ELEV: 354.6 SURVEYED
 22 ACREAGE: 826
 > 23 RIGHT TRAFFIC: NO
 > 24 NON-COMM LANDING: NO
 25 NPIAS/FED AGREEMENTS: NGRY3
 > 26 FAR 139 INDEX:

RUNWAY DATA

	10/28	16/34
> 30 RUNWAY INDENT:	3,807	6,506
> 31 LENGTH:	75	100
> 32 WIDTH:	ASPH-G	ASPH-G
> 33 SURF TYPE-COND:	NONE	NONE
> 34 SURF TREATMENT:	30.0	42.0
35 GROSS WT: S	45.0	60.0
36 (IN THSDS) D	75.0	106.0
37 2D		
38 2D/2D2		
> 39 PCN:		

LIGHTING/APCH AIDS

	NPI - G / NPI - G	PIR - G / PIR - G		
> 40 EDGE INTENSITY:		HIGH		
> 42 RWY MARK TYPE-COND:		P4L / P4L	- / -	- / -
> 43 VGSI:	/	45 / 43	/	/
44 THR COSSING HGT.:	/	3.00 / 3.00	/	/
45 VISUAL GLIDE ANGLE:	N - N / N - N	N - N / N - N	- / -	- / -
> 46 CNTRLN-TDZ:	- N / - N	- N / - N	- / -	- / -
> 47 RVR-RVV:	N / N	N / N	/	/
> 48 REIL:	/	/ MALSR	/	/
> 49 APCH LIGHTS:				

OBSTRUCTION DATA

	A(V) / A(NP)	C / PIR		
50 FAR 77 CATEGORY	/	/	/	/
> 51 DISPLACED THR:	/	POLE / TREES	/	/
> 52 CTLG OBSTN:	/	20 / 58	/	/
> 53 OBSTN MARKED/LGTD:	/	260 / 722	/	/
> 54 HGT ABOVE RWY END:	/	400R / 549L	/	/
> 55 DIST FROM RWY END:	/	3:1 / 9:1	/	/
> 56 CNTRLN OFFSET:	20:1 / 20:1	Y / N	/	/
57 OBSTN CLNC SLOPE:	N / N		/	/
58 CLOSE-IN OBSTN:				

DECLARED DISTANCES

> 60 TAKE OFF RUN AVBL (TORA):	/	/	/	/
> 61 TAKE OFF DIST AVBL (TODA):	/	/	/	/
> 62 ACLT STOP DIST AVBL (ASDA):	/	/	/	/
> 63 LNDG DIST AVBL (LDA):	/	/	/	/

> 110 REMARKS

A 017 AFTER HRS SVC: 229-382-2545.
 A 058 RWY 16 40 FT TREE, 190 FT FM EOR, 491 FT RIGHT.
 A 070 FUEL 24 HR CREDIT CARD SVC AVBL.
 A 081 ACTVT HIRL RWY 16/34, PAPI RWYS 16 AND 34, MALSR RWY 34 - CTAF.
 A 110-001 (E99) USED FOR MAINT.
 A 110-002 (CONTACT TITLE) CHAIRMAN HENRY TIFT MYERS AIRPORT AUTHORITY.

111 INSPECTOR: (S)

112 LAST INSP: 02/26/2026

113 LAST INFO REQ: 08/14/1993

AIRPORT MASTER RECORD

Data Source: https://www.faa.gov/air_traffic/flight_info/aeronav/aero_data/

PRINT DATE: 5/16/2026
AFD EFF 05/14/2026